



MZ2S



S. C. R. Unit

(2 Fuse use)

M
Z
2
S

MZ2S									Model No.	
—	—	—	—	—	—	—	—	—		
0304L	0504L	0804L	1004L	1204L	1604	2004	2504	3004		
									Dimensions (Unit: mm)	
30A	50A	70A	100A	120A	160A	200A	250A	300A	Load Current Rating (A)	
100~500V									Load Voltage (V)	
Operating: 0~50°C, Storage: -10~70°C									To Take Pressure Ambient Temp.	
0~90%									RH	
—									Auxiliary Power	
0.6A									Min Load Current	
—									Off State Leakage Current	
50Hz / 60Hz									Power Consumption	
—									Frequency Range	
—									0~20mA	Control Type (Input)
•									4~20mA	
—									0~5V	
—									1~5V	
—									0~10V	
—									2~10V	
AC 2000V (1 min input & output to ground)									Input Resistance	
—									Isolation Voltage	
3 phase 2 fuses									Alarm	
—									Notation	
Approx. 1800	Approx. 2200	Approx. 3475	Approx. 5400	Approx. 7000	Approx. 9400				Net Weight (g) (Include heat sink)	
<ol style="list-style-type: none"> 1. Zero cross control, 3 phase with 2 fuses. 2. Fuse included. 3. High accuracy with analog control. 4. 4~20mA can drive thyristor directly, auxiliary power supply is not necessary to make easy wire connection and maintenance. 5. Input signal 4~20mA available only. 6. CE Approval 									Features	